

vLinker Series upgrade instructions

1. Connect device

1> Bluetooth device (PinCode: 1234)




2> vLinker WIFI




2. Select device type


1> Bluetooth select port number




2> vLinker USB select port number, vLinker FS default baud rate(115200)




3>vLinker WIFI device select




3. Select update file



4. Start Update



5. Update completed, Power cycle the device to work



*If the upgrade fails, power cycle the device and upgrade again.